Results from portable Intermittent Fault Detector (IFD) Testing of Electrical Wiring Interconnection Systems (EWIS)

Test Location:

Weapon System: AH-64 Apache

Test Date: 9 Oct 2018



Unit Under Test (UUT): Black Engine Harnesses

Left (Cable ID: W185)Right (Cable ID: W186)

CONOPS:


- Each engine harness costs roughly \$11,000
- External damage to harness results in disposal
- Internal cable issues can be repaired but is not done by contracted shop in hangar 10 – they replace with new harness
- QA with conventional / traditional continuity tests (Digital Multi-Meter (DMM)) is the current test procedure for these harnesses




Test Procedures:

- Left (Cable ID: W185) AutoMap[™] completed
- Right (Cable ID: W186) AutoMap[™] completed found two additional connections different than Left (Cable ID: W185)
 - o Connection #1 was J121 Pin 4 to J121 Pin 10
 - Connection #2 was shield on J21
- Left (Cable ID: W185) Continuity failed due to additional connections as described above
- Left (Cable ID: W185) Intermittence test passed certified intermittent free
- Right (Cable ID: W186) Continuity passed
- Right (Cable ID: W186) Intermittence failed on J39 2,3,4, and shield
 - Lock ring had been overtightened causing poor engagement





Fault Isolation Graphic displaying Intermittent Events on connector J39 wires 2, 3, 4 and shield



Right (Cable ID: W186) Lock Ring Overtightened

- Right (Cable ID: W186) Intermittence failed on J39 2,3,4, and shield (cont.)
 - o No Fault Found (NFF) Cycle Begins as harness passed continuity
 - Harness would have been installed on AH-64 Apache
 - Operational Conditions → intermittent in flight → operational failure
 - Pass continuity on the ground = No Evidence of Failure (NEOF)

Results:

- Right Black Engine Harness (Cable ID: W186) would have been installed on aircraft and would have experienced an operational failure
- Intermittent Fault Detection technology detected and isolated the faults and prevented the NFF cycle

Recommendations:

- Based on CONOPS, it is recommended that all AH-64 Black Engine Harnesses be quality inspected with IFD prior to install
- Expand IFD testing to additional AH-64 EWIS